


机型 model	BD500			零件供应状态表 Requirements Sheet For Status Of Supplied Part	使用单位 use unit	编号 serial NO.						
每机数量 quan./shipset	8	图号 drawing NO.	C01551221-0038		供应单位 supplying unit		S2B-E62800-603 A					
供应状态说明 Instruction for supplied status				供应状态草图 sketch of status of supplied part								
1. 钻 2 个 $\Phi 2.1\text{mm}$ 导孔, 钻 1 个 $\Phi 2.4\text{mm}$ 装配孔, 位置如草图, 具体尺寸见 MBD.				 <table border="1" data-bbox="1568 829 2150 941"> <tr> <td>*</td> <td>Pilot hole $\Phi 2.1\text{mm}$ 导孔</td> <td>2</td> </tr> <tr> <td>■</td> <td>Coordinated hole $\Phi 2.4\text{mm}$ 装配孔</td> <td>1</td> </tr> </table>			*	Pilot hole $\Phi 2.1\text{mm}$ 导孔	2	■	Coordinated hole $\Phi 2.4\text{mm}$ 装配孔	1
*	Pilot hole $\Phi 2.1\text{mm}$ 导孔	2										
■	Coordinated hole $\Phi 2.4\text{mm}$ 装配孔	1										
2. 其余状态按 MBD												
As shown in the sketch, location per MBD. Drill $\Phi 2.1\text{mm}$ pilot holes(2), Drill $\Phi 2.4\text{mm}$ coordinated holes(1), the other condition per MBD.												
自 批 SAC0033 架开始按此状态表供应 from batch shipset per this status												